

Installation and Maintenance Manual for ExnA, ExtC & ExtB

TECO Electric Europe Ltd
Westbrook Road
Trafford Park
Manchester
M17 1AY

INSTALLATION & MAINTENANCE INSTRUCTIONS

This instruction manual is for TECHNICAL USE ONLY, NOT FOR COMMERCIAL PURPOSE. The warranty is limited to coverage expressed in your sales contract. Documentation of storage, transportation, installation and examination, if required, shall be inquired of TECO's service center before start and maintenance.

BEFORE INSTALLATION & USE

- 1. Ensure nameplate data corresponds with your requirements
- 2. Ensure the motor is undamaged
- 3. Remove any shaft clamp (but refit prior to transportation)
- 4. Slowly rotate the shaft to ensure free movement
- 5. Ensure the mounting/shaft orientation design and drain hole positions are correct for the application
- 6. Eyebolt(s) and any other lifting means must be tight before use



WARNING

The following safety precautions must be observed:

1. Electric rotating machinery and electricity can cause serious or fatal injury if the motor is improperly installed, operated or maintained. Responsible personnel must be fully trained to understand the hazards to themselves and others before being involved in installing, operating, maintaining and decommissioning electric motors. European Union Safety information can be obtained from such as:

EN60204-1; EN60034; EN292; EN294; IEE Wiring Regulations

Particular industries and countries have further safety requirements. Refer to their trade & safety bodies.

- 2. AEXCB Ex nA Ex tB & Ex tC Certification Products Special Conditions For Safe Use
- a. All terminal nuts and screws, whether used or not, shall be correctly tightened.
- b. Supply connections shall be made with ring type terminal lugs which have insulated shanks. Clearance distances shall not be reduced when tightening connections.
- c. On auxiliary terminals the conductor insulation shall extend to within 1 mm of the terminal throat.
- d. There shall be no loose conductor strands on any terminal.
- e. The drain plugs (when fitted) shall be replaced immediately after use and sealed with an appropriate sealing compound.
- f. The brass terminal links shall be connected correctly so as not to reduce the clearance distances.
- g. The incoming mains cables are to be provided with insulated crimped terminals lugs to maintain the minimum clearance distance.
- h. The cable glands are to be provided with sealing gaskets to maintain the IP rating.
- 3. When servicing, all power sources to the motor and to the accessory devices should be de-energized and disconnected and all rotating parts at standstill.

- 4. Lifting means, such as eyebolts, on the motor are for lifting only the motor itself. Assemblies which are not part of the motor must be removed prior to using the motor lifting means. When more than one lifting means is provided on the motor, all must be used together, for instance by attaching a supporting chain to each, to share the load. Ensure that lifting means are fully attached to the motor before lifting.
- 5. Suitable ear protection must be worn near machinery emitting high audible noise to reduce the noise reaching the ear to a safe level.

 Refer to EN 60034-9 for further information on noise from rotating electrical machines.
- 6. Safety guards and other protective devices must neither be bypassed nor rendered inoperative.
- 7. The motor must be earthed. Refer to relevant standards such as EN60204-1, IEE Wiring Regulations etc.
- 8. A suitable enclosure must be provided for the motor to prevent access to moving parts. Extra caution should be observed around a motor that is automatically started or has automatic resetting relays or is remotely started in case such starting means has not been properly disabled and the motor starts unexpectedly.
- 9. A Ensure all shaft keys present on moving parts are fully captive before the motor is started.
- 10. A Ensure adequate safeguards have been made to protect against the consequences of a brake failure, particularly on applications involving overhauling loads.
- 11. TECO UL listed explosion proof motors must only be used in countries where the UL certification is recognized as being appropriate for the application. They are constructed to comply with the label service procedure manual and repairs to them must be made by TECO or a UL listed service center in order to maintain the UL listing.
- 12. A Protect the motor from overload, preferable by monitoring the winding temperature. TECO can fit thermostats to give indication that the winding is getting too hot and the thermostats can be connected to switchgear that will automatically trip on the signal from the thermostats.
- 13. Capacitors such as in single-phase motors may remain charged even when isolated from the mains supply. Discharge capacitors and earth their terminals before handling any connections.
- 14. All TECO UL listed Explosion Proof motors have temperature limiting devices in the motor enclosure to help prevent excessive external surface temperature of the motor in accordance with UL standards. Terminals (P1 \ P2) of thermal protectors

in these motors must be connected to the motor control equipment according to the connection diagram inside the terminal box.

15. If regressing is to be carried out with the motor running, ensure only properly trained personnel do it and that live and moving parts are fully guarded.

16. Dust Ignition Proof motors Ex tD or the motors with degree of protection greater than IP55, the terminal box must be sealed with gaskets to prevent ingress of dust and water. If removed, gaskets must be glued with Loctite 330 or 596 or MXBON TB625 or Hylomar Blue.

Location

- 1. Drip proof motors are intended for use where the atmosphere is relatively clean, dry, well ventilated and non-corrosive. Refer to EN 60034: Part 5 for more detailed information on suitability of a particular enclosure rating.
- 2. Totally enclosed motors may be installed where dirt, moisture or dust are present and in outdoor locations. Refer to EN 60034: Part 5 for more detailed information on suitability of a particular enclosure rating.
- 3. Explosion proof motors have many different categories because hazardous atmospheres can consist of many different gases, which may or may not be present continuously. Individual countries/users can differ in their safety requirements so the suitability of an explosion proof motor for any particular hazardous location must be assessed against the standards and specifications in force for that location. They must not be used in hazardous locations unless it has been established that they do comply with the safety standards and specifications in force for that location.
- 4. Before installing, operating or carrying out maintenance services on electric motors used on hazardous locations, care must be taken on the following: and understood.
- All requirements included in the applicable standards must be understood accordingly.
- Instruction Marking as listed in Annex and
- The Ambient temperature limits are as follows: Ex n, ExtC and ExtB do not exceed 55°C
- When anti-condensation heaters are fitted they are to be interlocked such that they can only be energized when the motor is de-energized.
- The protection class and the IP-class of the cable entry devices when fitted must be at least the same as those of the terminal boxes.
- The cable glands are to be provided with sealing gaskets to maintain the IP rating.
- When the motor on delivery, cable entry will be fitted with plastic plug to prevent mist and dust entering. But right after motor be installed, the surplus or unused cable entry must be plugged with ExCB certified plug (e.g. IEC Ex d, Ex e or Ex n) to the terminal box.

- The brass terminal link should be connected correctly and power supply bare wire can't bulge over the bushing nut so as not to reduce the clearance distance.
- The incoming mains cables are to be provided with insulated crimped terminals lugs maintain the minimum clearance distance.

to

- In order to avoid bolt broken or wiring released, the nut tightening torque of terminal block and bushing must be observed according to table below
- a. The motor for Ex nA, Ex tC & Ex tB

Frame size	Thread sizes	Tightening torque (Nm)	Terminal form
63 – 71	M4	0.8 – 1.1	
80 – 112	M5	1.6 – 2.2	
132 – 180	M6	2.7 – 3.7	PY EYE
200 – 250	M8	6.7 – 8.9	
280 – 315	M10	12.3 – 17.9	Tamainalblada
	M12	22.6 – 30.4	Terminal block
	M16	54.9 – 74.5	
			Rushing
			Bushing

	MOTOR TYPE - HORIZONTAL FOOT	MOTOR TYPE VERTICAL FLANGE /
	HORIZONAL FOOT / FLANGE	HORIZONTAL FLANG
Protection	Premium	Premium
	Efficiency	Efficiency
	IE3	IE3
Ex nA	NLCA	NLCA
Ex tD	DLCA	DLCA
FRAME	80~315	80~315

5. Chemical duty enclosed motors are designed for installation in locations where they may encounter corrosive substances and/or high moisture.

Note: In all locations the surroundings must not obstruct the normal flow of ventilating air to and from the motor.

MOUNTING

1. Ensure the orientation of the frame is appropriate for the design of the motor. For instance, motors designed for B3 (horizontal shaft), may not be suitable without modification for V5 (vertical shaft) because any drain holes will be in the wrong position, additional fixings may be required to prevent the shaft sliding through the bearings and different bearings may be needed to withstand the thrust force.

Drip proof motors may not be drip proof in the wrong orientation.

Consult TECO to establish whether a motor may be safely used in an orientation different from that ordered.

- 2. Where the motor is to be subject to a high degree of vibration (such as on a vibrating screen), high humidity (typically above 95%), abnormal ambient temperature (typically outside the range -20 to +45 $^{\circ}$ C), or high altitude (typically above 1000meter) ensure that the motor specification is appropriate.
- 3. When mounting the motor, ensure this is done securely using steel nuts and bolts through each of the fixing holes provided, fully tightened. Where the location is likely to cause rusting, such as in the presence of sea water, stainless steel fixing bolts may be an advantage. Where there is significant vibration, ensure there are shakeproof washers under the nuts.
- 4. Where the drain holes are to be left open, ensure they are guarded from access when the motor windings are connected to a power supply.
- 5. With a directly-coupled load ensure the motor and load shafts are accurately aligned and use a flexible coupling between them. Mounting bolts must be carefully tightened to avoid alignment changes and the alignment rechecked to ensure it is correct when the bolts are fully tight.
- 6. With a side-coupled load, such as a belt or gear drive, ensure the side force on the shaft will not damage the motor. Consult TECO if in doubt.
- 7. If motors mounted with the shaft upwards and water or liquid are expected to go down along the shaft part, the user must consider mounting some capable means to preventing it.

POWER SUPPLY AND CONNECTIONS

- 1. Wiring of the motor and its controller, overload protection and earthing should be in accordance with the current edition of the IEE wiring regulations, EN60204 and all local safety requirements.
- 2. Refer to the nameplate voltage, frequency and current to ensure the motor is correct for the material of wire and the power supply to which it is to be connected. Unless specified otherwise the motor may be assumed to be suitable for the nameplate voltage +/-5% and nameplate frequency +/-1%.
- 3. Connection diagrams for the motor are generally supplied with it, either on the nameplate, fixed to the motor or placed in the terminal box.
- 4. All TECO UL listed Explosion Proof motors have temperature limiting devices in the motor enclosure to help prevent excessive external surface temperature of the motor in

accordance with UL standards. Terminals (P1, P2) of thermal protectors in these motors must be connected to the motor control equipment according to the connection diagram inside the terminal box.

Start up

- 1. Initially, run the motor unloaded and establish that the rotation direction is as required. If not, switch off and when rotation has stopped:
- if the motor is a three phase motor interchange any two phases.
- if the motor is a single phase motor interchange the connections to the auxiliary winding circuit, leaving the connections to the main winding unchanged.
- 2. Then start the motor fully loaded. If it does not start quickly and run smoothly, switch off immediately and when rotation has stopped, isolate from the power supply and examine the assembly for mechanical faults or poor connections.
- 3. If there is excessive vibration it could be caused by poorly-aligned couplings, loose mounting bolts, lack of rigidity in the supports, transmitted vibration from adjacent machinery etc. Excessive vibration can lead to motor damage, for instance to the bearings making them noisy, and hence vibration should be minimized.
- 4. Ensure the current drawn is commensurate with that shown on the nameplate and that the currents in each phase are similar.
- 5. If a single phase motor does not start, this may be due to the internal starting switch not closing when the rotor is stationary or a faulty starting capacitor.

Long term storage and humid environments

1. If the motor has been stored for an extensive period or subjected to adverse moisture conditions, ensure the insulation resistance is greater than 1M Ohm before switching on. Also, regrease the bearings and if they are rusty, replace them.

When the insulation resistance is not greater than 1M Ohm, dry out the motor as described below. If after drying out the insulation resistance is still not greater than 1M Ohm, the motor will need repairing.

2. Place

- (a) High and dry, well-ventilated without direct sun, dust or corrosive gas. (b) Not located near to a boiler or freezer.
- (c) Entirely free from vibration and easy for movements. (d) Motors should be put on pallets to prevent moisture.

Drying out

This may be carried out either:

- 1. By baking in an oven at up to 90°C. Ensure the interior and exterior of the oven are well ventilated.
- 2. By locking the rotor so it cannot move and connecting a low voltage to the motor windings. Gradually increase the voltage from zero until the current is about one third the rating plate value. Trim the voltage as necessary so that the winding temperature remains below 90°C.

Drying out is complete when the insulation resistance stops changing.

Maintenance

Inspection

Inspect the motor at regular intervals. Ensure it is kept clean with clear ventilation openings, there is no excessive vibration and noise emitted from the motor are normal. Ensure fixings and fasteners have not loosened nor so corroded that either their strength has been reduced significantly or earthing has been impaired, Ensure also that electrical connections are tight and uncorroded and that earthing is intact.

Inspect shaft seals and terminal box gaskets to ensure they are in position and not significantly worn. Contact TECO if the seal/gasket types on the motor are unknown. Examine the paint finish and repaint if necessary to avoid excessive corrosion. Ensure that shaft couplings are fixed firmly and that shaft alignment is correct. Ensure also that there is no buildup of liquid inside the motor that would adversely affect its performance and drain if there is.

Lubrication

Motors with double shielded (suffix "zz" on bearing type) bearings are lubricated for life and cannot be relubricated.

Larger frames (usually Frames 200 and above, 180 2 pole) in particular have regreasing facilities. These motors are shipped already-greased and the grease should be replaced at regular intervals. The length of the interval varies with size of motor and how it is used.

The table below gives a guide to relubrication intervals. Excessive or too frequent lubrication may actually damage the motor.

If roller bearing is used, add a small quantity of grease when abnormal sound occurred from the bearings. If this sound, such as shi-shi or thru-thru, disappears temporarily after regreasing, it is normal condition and can operate as it is, as long as the temperature rise of the bearing is normal.

		Relubrication p	Relubrication period		
Rated output kW	Poles	Standard conditions	Severe conditions	Extreme conditions	
0-30	4 upwards	7 years	3 years	6 months	
37-75	4 upwards	210 days	70 days	30 days	
90-110	4 upwards	90 days	30 days	15 days	
132-600	4 upwards	90 days	30 days	15 days	
0-18.5	2	5 years	2 years	3 months	
22-75	2	180 days	60 days	30 days	
90-110	2	90 days	30 days	30 days	
132-600	2	90 days	30 days	15 days	

For other ratings please refer to TECO

Definitions

Standard conditions: 8 hour operation per day with rated or light loading in a clean low-vibration environment

Severe conditions: 24 hour operation per day with rated/light loading or in a dirty/dusty environment or where the motor is subject to vibration/light shock loading

Extreme conditions: Where there is heavy shock loading or high vibration or a very dirty/dusty environment



A Regreasing operation

If regreasing is to be carried out with the motor running, ensure it is done only by properly-trained personnel and that live and that live and moving parts are fully quarded.

Ensure the grease exit is open and the grease nipple is clean. Attach a low pressure grease gun to the nipple and pump in grease until clean grease emerges at the grease exit.

Remove the grease gun. Fully guard live and moving parts and then run the motor for 10-30 minutes ensuring that any surplus grease is properly disposed of, and then refit any grease exit plug.

Grease Type

Ensure only the correct type of grease is used. Greases incompatible with that in the bearings can greatly reduce the bearing life. Consult TECO if you are not sure of the type supplied in your TECO motor.

TECO standard regreasable motors use MULTEMP SRL or ALVANIA RL3 grease. Information on the lubrication nameplate shall be followed as first priority.

Spares

Use only genuine TECO spares or alternatives recommended by TECO When ordering, please give full nameplate details and in particular:

Frame Number Type Poles kW Serial Number Quantity required

Disposal of unserviceable and end-of life motors and parts.

The motors consist by weight, primarily of cast iron, steel, copper and aluminium alloy.

They also have some plastic material for instance, for insulation, sealing and termination of conductors and varnish for impregnation of the winding. The fan and internal baffles may be of plastic.

Typically the metals are recyclable by burning off in a furnace the non-metallic material and either breaking or melting the metals into their constituents. Ensure the gases given off during the burning do not pollute.

The furnace may need a license or evidence giving them exemption (for instance if they are small) to carry this out.

The above suggestions for recycling should be taken as guidance only. Dispose of according to the regulations in force locally.

Annex

Certification Marking & Number: IECEx Ex n / Ex tb / Ex tc

Frame	Marking			Certificate Number	Standard
	Ex nA	Ex tb / Extc	Atex	IECEx-	
80-315	Ex nA IIC T3 Gc	Ex tb IIIC T135°C Db IP66 Ex tc IIIB T135°C Dc IP55	Baseefa 17ATEX0073X Baseefa 17ATEX0076X		IEC 60079-0: 2011 IEC 60079-7: 2015 IEC 60079-31: 2013